

## Screw Press Lessons

Presented by: Leo R Gaudette Chief Operator Town Of Merrimack NH



# Background

Population of 28,000
Home of Anheuser-Busch brewery
5.0 MGD secondary WWTF circa 1969
1.8 MGD current flows
Agitated bin composting facility circa 1993



# **Reasons for upgrade**

Belt press and other equipment had reached end of useful life
Press was inefficient and 30 years old
Some equipment was 40 years old
Required high level of maintenance
Staff reductions ability to run un attended 24/7



## **Original Belt Press**





# **Technology Selection**

**3** proven technologies Screw press Rotary drum press Centrifuge 1 week trial for each Life-cycle cost estimate Capital, labor, spare parts, energy, polymer, disposal, trucking Also noise, odor containment, filtrate capture, # of installations



### Net Present Value

Life cycle cost in NPV Screw Press - \$14.4 to \$15.1 M Rotary Drum Press - \$15.61 M Centrifuge - \$15.64 M Screw press ranked highest with non-monetary factors Screw presses selected as best and most cost-effective dewatering option



## Importance Of fiber Content

25% or higher	27%
20% to 24.9%	25%
15% to 19.9%	23%
10% to 14.9%	18%
5% to 9.9%	15%



#### **ISSUES**

- Did not meet performance initially (25% Cake 95% Capture)
- Flooding of polymer containment area
- Flooding concerns press containment and floc tank
- Sludge pushing out of hatches (Cake Cutter)
- High amperage on drive unit
- Premature conveyor liner wear (Not FKC)
- Loss of throughput (Importance of Inspections)
- Build up on screw
- Scaling (Water hardness)



## Screw Press Reflighting



Changed from single stage to two stage and increase compression 3.0 to 3.75 Increased open area of some of the screens



## Polymer Tank Room Flood







## Sludge Coming Out of Hatches





## Sludge Cake Cutters





# Screw Conveyor Wear





### Overview Screen





### Conveyor Control



CONV. 4	CONV. 5
STOP DELAY	STOP DELAY
TER CONTAINER	AFTER CONTAINER
SWITCH	SWITCH
200 SEC	200 SEC



## Polymer Control





## Pump Controls

#### COMBINED SLUDGE PUMPS



#### CSP STORAGE TANK LOW PUMP INTERLOCK S.P. 0.1 FT



COMB. SLUDGE	COMB. SLUDGE
OFF	OFF
HAND	HAND
RUN	STOP
H-O-R IN REM	H-O-R IN REM
READY	READY
SPEED	SPEED
20.0 %	0.1 %
13.1 AMPS	0.0 AMPS
MAN S.P.	MAN S.P.
0.0 %	0.0 %

EXIT



### Flow Totals

RSP FLOW TOTALS						
COMBINED SLUDGE		POLYMER				
		DIL WATER		NEAT POLYMER		
FLOWRATE	30.2	7.9	GPM	FLOWRATE	0.0843	GPM
TODAY	6.890	2	GAL X 1000	TODAY	27.7	GAL
YESTERDAY	36.350	8	GAL X 1000	YESTERDAY	93.3	GAL
THIS MONTH	213.78	58	GAL X 1000	THIS MONTH	13653.2	GAL
THIS YEAR	7538	1753	GAL X 1000	THIS YEAR	37750	GAL
NON RESET	170090	19	GAL X 1M	NON RESET	136	GAL
		L		POLYMER MAKE	DOWN 0.	1113 %

#### **ELAPSED TIME METERS**

ROT. SCREW PRESS 22788.5 SLUDGE FLOC MIXER 22256.8 NEAT POLYMER PUMP 1 12046.1 NEAT POLYMER PUMP 2 10047.6 POLY WTR. BOOSTER 22.0 COMB. SLUDGE PUMP 1 11514.1 COMB. SLUDGE PUMP 2 10666.6

FLUSH WTR. BOOSTER 13612.0 CONVEYOR 1 22886.2 CONVEYOR 2 22900.5 CONVEYOR 3 22910.6 CONVEYOR 4 11408.4 CONVEYOR 5 11641.4

EXIT



### Alarm Controls

#### ROT. SCREW PRESS ALARM CONTROL





Exit



#### Weekly Monthly Maintenance

- Clean head box screens
- Clean head box and top sprayers
- Hose, pressure wash or clean outside of screens (Depends)
- Drain clean the floc tank
- Clean polymer static mixers and flush linesClean covers



# **Yearly Inspections**



Check for other unusual conditions



#### **Yearly Inspections**



Check Flight Wear and Tolerances and Screen Wear



#### **Yearly Inspections**

#### SCREW PRESS INSPECTION CHECKLIST

PRES	SS#: #1 DATE: 9/12/2014		INSPECTOR Keith Lawler			
ITCM			COMMENTS			
TIEM		Y	COMMENTS			
1	SCREEN DEFORMATION/DAMAGE LOW PRESSURE DRUMS EXTERIOR SURFACE		No wear or damage seen			
2	SCREEN DEFORMATION/DAMAGE HIGH PRESSURE DRUMS EXTERIOR SURFACE	1	No wear or damage seen			
3	INSPECT FOR CORROSION OF HIGH AND LOW PRESSURE DRUM SECTIONS/BOLTS	1	OKAY, no corrosion			
4	CHECK CLEARANCES BETWEEN SCREW FLIGHT AND INSIDE OF SCREEN	1	Clearance in the inlet end of press was adjusted, inlet clearances adjusted to <.1~.2 mm			
5	INSPECT INTERIOR SURFACE OF HIGH PRESSURE SCREENS FOR WEAR AND THINNING	1	Screens are in good shape.			
6	INSPECT INTERIOR SURFACE OF LOW PRESSURE SCREENS FOR WEAR AND THINNING	1	Screens are in good shape			
7	INSPECT SCREW FLIGHT AT HIGH PRESSURE SECTION FOR EXCESSIVE WEAR	1	HP flight in good shape. Teflon coating on screw shell and flights is worn off in large area			
8	INSPECT SCREW FLIGHT AT LOW PRESSURE SECTION FOR EXCESSIVE WEAR		LP flight in good shape. Teflon coating on screw shell and flights in good shape but is coated with brown thick rough material.			
9	VERIFY SPRING CONE IS FREE TO MOVE. DISASSEMBLE SPRING ARBORS AND INSPECT	1	No threads showing, FKC adjusted to 4- 3/4 of exposed threads. Do not readjust.			
10						
11	INSPECT SPEED REDUCER, AND ALL OIL SEALS FOR OIL LEAKAGE	1	OKAY			
	VERIFY PROPER LUBRICATION OF:					
12	a) SPEED REDUCER	1	OKAY			
	b) INLET STAND BEARING	1	OKAY			
	c) SPRING CONE ARBORS	1	OKAY			
13	VERIFY ALL BOLTS ARE TIGHT	1	OKAY			



#### Performance





# **Final Thoughts**

Met or exceeded all goals and expectations •Over 60% reduction in composting amendment -\$50,000 savings Allowed for more merchant sludge increase revenues keep sewer rates low Aid in phosphorus removal (Spread out loadings) One operator freed up for other tasks Improved plant performance No odor control chemicals required - \$10,000 savings

